

1/38







Fig. 1





4/38



5/38







FIG. 5




L R







9/38








FIG. 10





II II II II


12/38




13/38







II II II II II














Fig 17
















24/38







11 11 11 11




FIG. 26

27/38







FIG. 29


FIG. 30




29/38


















35/38



614

An arrow labeled '614' points horizontally to the left, towards the cross-section of the material.

FIG. 35

614

An arrow labeled '614' points horizontally to the right, towards the cross-section of the material.




FIG. 38

36/38




FIG. 39

37/38

